

AirTrack Factory

GENERAL TIPS

STORE THE GLUE AT ROOM TEMPERATURE.

GLUE IS USABLE WITHIN 12 MONTHS AFTER OPENING.

KEEP OUT OF REACH OF CHILDREN.

IT TAKES 48 HOURS UNTIL GLUE IS FULLY HARDENED.

WORK IN A WELL-VENTILATED SPACE.

PUT THE EQUIPMENT ON A CLEAN AND SAFE SURFACE.

KEEP A CLOTH NEARBY TO REMOVE ANY POSSIBLE EXCESS OF GLUE.

AFTER 48 HOURS CHECK THE LEAK WITH SOAP TO SEE IF YOU SUCCEEDED.

CHECK THE AIR PRESSURE WITH A MANOMETER



FACEBOOK: AIRTRACK FACTORY
INSTAGRAM: @AIRTRACKFACTORY
YOUTUBE: AIRTRACK FACTORY
WEBSITE: WWW.AIRTRACKFACTORY.COM
EMAIL: INFO@AIRTRACKFACTORY.COM

AIRTRACK FACTORY B.V.
BIJSTERHUIZEN 11-78
6546AS NIJMEGEN
THE NETHERLANDS



REPAIR INSTRUCTIONS



AirTrack Factory

HOLE REPAIR STEPS

CHECK WITH THE SOAP TO LOCATE THE LEAK. 1

MARK THE LEAK. 2

CHOOSE THE RIGHT AIRTRACK PATCH. IT SHOULD AT LEAST COVER AN EXTRA 1CM AROUND THE LEAK. 3

CLEAN THE AIRTRACK PATCH AS WELL AS THE SPOT AROUND THE LEAK WITH THE ALCOHOL PATCH. 4

RUB THE AIRTRACK PATCH AS WELL AS THE SPOT AROUND THE LEAK WITH GLUE AND LET IT DRY FOR 5 MINUTES. 5

PUT THE GLUED AIRTRACK PATCH ON THE LEAK, AND PRESS FIRMLY, REMOVE ANY EXCESS GLUE WITH A PIECE OF CLOTH. 6

PUT A PIECE OF CARTON ON THE AIRTRACK PATCH WITH A HEAVY OBJECT AND WAIT 48 HOURS WITHOUT MOVING IT. 7

NECESSITIES

- GLUE** (INCLUDED)
- AIRTRACK MATERIAL** (INCLUDED)
- ALCOHOL PATCH** (INCLUDED)
- SOAP** (EXCLUDED)
- PENCIL** (EXCLUDED)
- (OPTIONAL) **MASKING TAPE** (EXCLUDED)
- OLD CLOTH** (EXCLUDED)
- PIECE OF CARTON** (EXCLUDED)
- HEAVY OBJECT** (EXCLUDED)



SEAM REPAIR STEPS

1 CHECK WITH THE SOAP WHERE THE LEAK IS LOCATED.

2 OPEN (IF NECESSARY) THE SEAM CAREFULLY WITH THE SCREWDRIVER.


3 TAPE THE AIRTRACK WITH THE MASKING TAPE TO PREVENT GLUE LEAKING OR SCRATCHING THE AIRTRACK WITH YOUR SCREWDRIVER.

4 CLEAN THE SEAM AND THE AREA YOU'RE GOING TO GLUE, WITH THE ALCOHOL PATCH.

5 PUT GLUE ON THE END OF THE SCREWDRIVER AND FILL THE SEAM. WAIT 5 MINUTES TO LET THE GLUE DRY BEFORE APPLYING PRESSURE.

6 PUT PRESSURE ON THE SEAM AND REMOVE ANY EXCESS OF GLUE WITH THE CLOTH.

7 REMOVE THE MASKING TAPE.



NECESSITIES

- GLUE** (INCLUDED)
- ALCOHOL PATCH** (INCLUDED)
- SOAP** (EXCLUDED)
- (OPTIONAL) **MASKING TAPE** (EXCLUDED)
- OLD CLOTH** (EXCLUDED)
- OLD FLAT SCREWDRIVER** (EXCLUDED)